Conversion Formulas

inch x 25.4 = mmfoot x 304.8 = mmmile x 1.609 = km



 $mm \times 0.03937 = inch$ $meter \times 39.37 = inch$ $km \times 0.6214 = mile$

Fahrenheit to Celsius: °C = °F - 32 x 5 ÷ 9 Celsius to Fahrenheit: °F = °C x 9 ÷ 5 + 32

Mill and Lathe Conversions

To Find:			Formula:
Revolutions Per Minute	RPM	=	(SFM x 3.8197) ÷ D
Surface Feet Per Minute	SFM	=	RPM x D x 0.2618
Surface Meters Per Minute (Metric)	SMPM	=	SFM x 0.3048
Inches Per Minute Milling Feedrate	IPM	=	FPT x T x RPM
Feed Per Tooth Mill	FPT	=	IPM ÷ (T x RPM)
Feed Per Revolution	FPR	=	IPM ÷ RPM
Inches Per Minute Lathe	IPM	=	IPR x RPM
Metal Removal Rate	MMR	=	WxdxF
Advance Per Revolution (Inches)	ADV/R	=	F÷ RPM

Threads

Mill Tapping Feedrate	IPM	=	1 ÷ TPI x RPM
Latte The and a discourse of a section (T)	IDD	_	4 · TDI

Lathe Threading Feedrate (Thread Lead) IPR

Major Dia. of Tap - % of Thread Height x .01299 Tap Drill Size

TPI x Major Dia. of Tap - Drill Dia. Percent of Full Thread =

1 ÷ RPM x Metric Pitch Mill Tapping Feedrate (Metric)

Tap Major Dia. (mm) - % of Thread Height x Metric Pitch Tap Drill Size (Metric)

76.980

Basic Major Dia. (mm) x 76.980 - Drilled Hole (mm) Percent of Full Thread (Metric)

Metric Pitch

Miscellaneous

Radius of Circle	=	Circumference x 0.159155
Diameter of Circle	=	Circumference x 0.31831
Circumference of Circle	=	D x 3.1416
Area of Circle	=	R2 x 3.1416
Cutting Time in Minutes (Mill)	=	L÷IPM
Cutting Time in Seconds (Lathe)	=	Distance to go x 60 sec
		IPR x RPM

Abbreviations and Measurement Units

D	=	Diameter of Milling Cutter or Lathe Part	SFM	=	Surface Feet per Minute
d	=	Depth of Cut	SMPM	=	Surface Meters per Minute
FPR	=	Feed per Revolution (in Inches)	T	=	Number of Teeth in the Cutter
FPT	=	Feed per Tooth (in Inches)	TPI	=	Threads per Inch
IPM	=	Inches per Minute (Table Travel Feedrate)	W	=	Width of Cut
IPR	=	Inches per Revolution	℃	=	Degrees Celsius
L	=	Length of Cut (Inches)	°F	=	Degrees Fahrenheit
RPM	=	Revolutions per Minute (Spindle Speed)			